

VEHICLE INSPECTION REPORT

PE63MZU

Daf LF 45.140

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 29/10/2013

VIN XLRAE45FF0L432001

Axle Combi 4x2

Year 2013

Body Style Box Van

Rear Suspension Steel

Mileage 922,321 Km Warranted

MOT Due 31/08/2026

Tail Lift Cantilever

Fuel Type Diesel

Cab Type DAY CAB

Colour RED

Gearbox MANUAL

WARNING LIGHT ON DASH

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4


OSO1


OSO2

OSO3


OSO4

Photos





Condition Check



Damage Photos




1: Wing osf
Scratched
Over 25mm Thru Paint

2: Bonnet
Scratched
Over 25mm Thru Paint



3: Fog Lamp Surround nsf
Broken
Replace

4: Bumper Front
Rusted
Over 5mm



5: Wing nsf
Scratched
Over 25mm Thru Paint

6: Door Mirror Assy nsf
Broken
Replace



7: Door nsf
Scratched
UpTo 25mm Thru Paint

8: Other
N/A
N/A



9: Qtr Panel nsr
 Scratched
 Over 25mm Thru Paint

10: Other
 N/A
 N/A



11: Door Mirror Assy osf
 Scuffed (Unpainted)
 Over 100mm

12: Door osf
 Chipped
 Edge Chip



13: Door osf
 Scratched
 Over 25mm Thru Paint

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK	
			No Excessive Smoking	OK	
EML light illuminated	OK		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	OK	