

VEHICLE INSPECTION REPORT

PK67VGA

Daf CF 450

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 09/11/2017

Year 2017

Mileage 1,206,315 Km
Warranted

Fuel Type Diesel

Colour RED

VIN XLRTGM4100G181528

Body Style Tractor Unit

Service history Yes

MOT Due 30/09/2026

Cab Type SLEEPER CAB

Gearbox AUTOMATIC

Axle Combi 6x2

Steering Combi Mid-Lift

Rear Suspension Air

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2


OSO3




OSO4

Features

- Air conditioning


Photos







Condition Check



Damage Photos



1: Wing of
Scratched
Over 25mm Thru Paint



2: Bumper Front
Chipped
Multiple Chips



3: Bumper Front
Dented
With Paint Damage

4: Wing nsf
Scratched
Over 25mm Thru Paint



5: Fog Lamp Surround ns
Scratched (Painted)
Over 25mm Not Thru Paint

6: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



7: Wing Front Arch Extension ns
Broken
Replace

8: Door osf
Scratched
Over 25mm Not Thru Paint



9: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm

10: Switches And Controls
Broken
Replace



11: Switches And Controls
Broken
Replace

Interior

Carpet Condition		Average		Upholstery Condition		Average	
Seat Condition		Average		Odour		-	
Engine Runs	OK			Gearbox 1st and Reverse Test	OK		
Brakes	OK			Clutch Slip Test from Static	OK		
Parking Brake	OK			Gearbox Static Gear Selection (engine running)	OK		
				No Excessive Smoking	OK		
EML light illuminated	OK			Oil warning light illuminated	OK		
Airbag light illuminated	OK			DPF light illuminated	OK		
ABS light illuminated	OK			Service indicator light illuminated	OK		